Docket No.: D75 (PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: TRACEY et al. Serial No.: 10/697,450

Confirmation No.: 7964

Issued: December 15, 2009
Patent No.: 7,632,080 B2

Patent No.: 7,632,080 B2
For: BEZEL ASSEMBLY FOR PNEUMATIC CONTROL

Examiner: Weinstein, Leonard J.

Art Unit: 3746

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected.

In the Claims:

In claim 48, at column 18, line 15, please correct line 15 as follows:

a rigid block having a pumping side and a port side, the port side having

This request does not involve correction of Applicant errors. Accordingly, no fee is required.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction. Applicant believes no fee is due with this request. However, if a fee is due, please charge our Deposit Account No. 504383 under Docket No. D75 from which the undersigned is authorized to draw.

Dated: March 4, 2011 Respectfully submitted,

/Marc J Gorayeb/ Marc J. Gorayeb Registration No.: 61,428

Attorney for Applicant

DEKA Research & Development Corp. 340 Commercial Street Manchester, NH 03101

Tel: 603-669-5139 Fax: 603-624-0573

PTO/SB/44 (09-07)

Approved for use through 08/31/2013. OMB 0551-033
U.S. Patent and Trademark Office, U.S. DEPARTMENT OF COMMERCE.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTC+1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. 7,632,080 B2 APPLICATION NO. ; 10/697.450

ISSUE DATE : December 15, 2009

INVENTOR(S) : TRACEY, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

In claim 48, at column 18, line 15, please correct line 15 as follows:

a rigid block having a pumping side and a port side, the port side having

Fax: (603) 624-0573